



1636 West North Temple • Salt Lake City, UT 84116 • 801-533-6071

\* M E M O R A N D U M \*

TO: File  
FROM: Richard B. Hall, P. E., Distribution Engineer  
SUBJECT: Field Review of Mill Creek Distribution System  
DATE: August 24, 1984

A field review of the subject system was undertaken on August 21, 1984, with the following in attendance:

Robert Byrnes  
Blaine Ipsen

Richard B. Hall  
Jerry L. Bronicel

The following items were observed and/or discussed:

- 1) Ray Alger Diversion - From Horse Creek - 9" Parshall Flume.
- 2) Kay Young Diversion - From Mill Creek - 12" Parshall Flume.
- 3) Mesa Irrigation Co. - From Dry Creek V.I.A. Warner Lake - 2" Parshall Flume damaged and needs to be replaced.
- 4) Shelly Tunnel - From Mill Creek to Ken Reservoir - Measured at Exit Portal.
- 5) Emma Walker & Deloy Lance - Mill Creek #5 - 1 foot Parshall Flume - Badly submerged - screen in front of weir. Blaine Ipsen is going to send the commissioner information on correction for submergance.
- 6) U.S.G.S. gaging station at abandoned power dam.
- 7) Mill Stream #2 and #1 ditches (#1 feeds #3 and #4) were not directly observed.