TO Office of State Engineer
Attn: Donald G. Norseth
State Capitol Building
Salt Lake City, Utah

BOARDMAN SPRING, THOMAS SPRING AND VICINITY

COMMISSIONER'S MONTHLY REPORT _____
Commissioner

Date Sept 30 — 1967

Report for Month of Sept 1967

Source and Point of Measurement	Day of the Month (Second Feet of Water)															
	1 / 16	2 / 17	3 / 18	4 / 19	5 / 20	6 / 21	7 / 22	8 / 23	9 / 24	10 / 25	11 / 26	12 / 27	13 / 28	14 / 29	15 / 30	31
I. Boardman Springs																
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)														*2.49		
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)							Gate completely up. All water to P.S.C.I.P.Co except water pipe would not take									
#3. Church ditch near to heading														1.53		
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)														0.644		
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake														⊗		
II. Thomas Spring																
#5. Above the Olsen house below the tracks														2.23		
III. Drain																
#6. Drain Channel near Railroad Shop and Burningham properties						estimate only								0.75		
IV. #8. Levie Ditch - Water to Church Farm, etc.		(#5 above plus #4 above)						Ditch full of water						3.00 estimate		
V. #9. Pump Water at Church Welfare Farm														None		

Submitted by E. Lewis Allen
E. Lewis Allen

For key to location numbers see drawing P-5107

* All going to P.S.C.I.P.Co

⊗ Wrong - Reading indicates 4.76 sec feet - water backed up [illegible] weir.