TO Office of State Engineer
Attn: Donald G. Norseth
State Capitol Building
Salt Lake City, Utah

BOARDMAN SPRING, THOMAS SPRING AND VICINITY

COMMISSIONER'S MONTHLY REPORT _____
Commissioner

Date May 26 1967

Report for Month of April 1967

Source and Point of Measurement	Day of the Month 1 / 16	2 / 17	3 / 18	4 / 19	5 / 20	6 / 21	7 / 22	8 / 23	9 / 24	10 / 25	11 / 26	12 / 27	13 / 28	14 / 29	15 / 29	31
	Second Feet of water															
I. Boardman Springs																
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)													~~0.905~~ 1.48	0.905		
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)													0.0	0.0		
#3. Church ditch near to heading													0.0	0.0		
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)													0.12	0.45		
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake													0.558	0.495		
II. Thomas Spring																
#5. Above the Olsen house below the tracks													0.990	1.04		
III. Drain																
#6. Drain Channel near Railroad Shop and Burningham properties													.15	0.2		
IV. #8. Levie Ditch - Water to Church Farm, etc.													1.11	None		
V. #9. Pump Water at Church Welfare Farm													None	None		

Submitted by E. Lewis Allen
E. Lewis Allen

For key to location numbers see drawing P-5107

All Boardman spring water going to P.S. CI Pipe
All Thomas " " " " Levee Ditch