TO Office of State Engineer
Attn: Donald G. Norseth
State Capitol Building
Salt Lake City, Utah

BOARDMAN SPRING, THOMAS SPRING AND VICINITY

COMMISSIONER'S MONTHLY REPORT _____
Commissioner

Date May 26 1967

Report for Month of May 1967

Source and Point of Measurement	Day of the Month 1 / 16	2 / 17	3 / 18	4 / 19	5 / 20	6 / 21	7 / 22	8 / 23	9 / 24	May 10 / 25	11 / 26	12 / 27	13 / 28	14 / 29	15 / 30	31
	Second Feet of Water															
I. Boardman Springs																
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)										1.59	2.49					
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)										—	—					
#3. Church ditch near to heading										0.0	0.0					
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)										0.45	0.55					
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake										0.495	0.346					
II. Thomas Spring																
#5. Above the Olsen house below the tracks										1.04	1.55					
III. Drain																
#6. Drain Channel near Railroad Shop and Burningham properties										0.75	0.5					
IV. #8. Levie Ditch - Water to Church Farm, etc.										0.0	1.56					
V. #9. Pump Water at Church Welfare Farm										0.0	2.5					

Submitted by E. Lewis Allen
E. Lewis Allen

For key to location numbers see drawing P-5107

Note Boardman Spring water flowing only to upper Users particularly P.S.C.I.P.Co. It has not joined Thomas Spring waters so far this year
Also note Thomas Spring water going only to levee users.
Church pump is giving water to [illegible]