TO Office of State Engineer
Attn: Donald G. Norseth
State Capitol Building
Salt Lake City, Utah

Last Report was Reading taken Apr 30, 1965

BOARDMAN SPRING, THOMAS SPRING AND VICINITY

COMMISSIONER'S MONTHLY REPORT _____
Commissioner

Date June 18 1965

Report for Month of May + June 1965

Source and Point of Measurement	Day of the Month (Second Feet of Water)															
	1 / 16	2 / 17	3 / 18	4 / 19	5 / 20	6 / 21	7 / 22	8 / 23	9 / 24	10 / 25	11 / 26	12 / 27	13 / 28	14 / 29	15 / 29	31
		June	June	May												
I. Boardman Springs																
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)		1.10	1.26	0.644												
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)		1.95	3.92	2.70												
#3. Church ditch near to heading		1.95	2.59	dry												
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)		2.37	4.40	0.370												
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake		0.705	1.33	2.72												
II. Thomas Spring																
#5. Above the Olsen house below the tracks		2.37	4.58	1.89												
III. Drain																
#6. Drain Channel near Railroad Shop and Burningham properties estimate's		0.111	0.20	0.133												
IV. #8. Levie Ditch - Water to Church Farm, etc.		dry	None	dry												
V. #9. Pump Water at Church Welfare Farm		dry	None	dry												
Total Boardman -		3.755	5.18	3.364												
Total Thomas + North Spring -		2.901	6.59	2.393												

Submitted by E. Lewis Allen
E. Lewis Allen

Note For key to location numbers see drawing P-5107

It has been a fairly rainy period just prior to June 18 readings.
Jessie J. Morrill was not using water turn on June 2
" " " " " " June 18