1991 COMMISSIONER REPORT for the LOWER JORDAN DISTRIBUTION SYSTEM

The water year for 1991 was a little better than the past three year's. The precipitation was up to near normal, but due to the previous drought years the water didn't go as far as normal.

Nearly all the duck clubs completed their dyke repair, except Jordan Fur & Reclamation and Farmington Bay.

Good rains in September made it so everyone was able to fill their ponds by October 5th.

January 26th was the low stream flow in the system taken at 21st South and the river. 203 cfs

June 2nd was the high stream flow taken on 21st 655 cfs.

The average flow for the year at the recorded gaging stations was:

Jordan River at 17th South	141 cfs	(264 cfs total 12/31/91)
Cudahay Lane & Jordan River	224 cfs	
Surplus Canal at 21st South	298 cfs	
Husted Dam & Surplus Canal	229 cfs	

Ambassador Cut and Gilmore and State Canal stations were checked several times but not recorded.

On October 12th the stream flow in the surplus canal was cut down so the Kern River pipeline could be installed across the canal. It was down for four days.

We still have a few problems in the system. The Ambassador Cut stream bed is still plugged up. The Lower Jordan and the State Canal need to be cleaned out. They are full of sand.

Fred Lewis from the North Point Duck Club is very unhappy with the Rudy Duck Club. The way they hold and discharge their water.

I think this problem should be discussed in this meeting.

LOWER JORDAN WATER COMMISSIONER
John E. Moesser

FORM NO. 201 5 M

STATE OF UTAH
OFFICE OF STATE ENGINEER

Daily Discharge in Second Feet of Jordan River

at Airdahay Lane for Lower Jordan 19 91

Day	Jan.	Feb	Mar.	April	May	June	July	Aug.	Sept.	Oct.	Nov.	Dec
1	125	0	0	0	0	0	0	0	0	0	0	0
2	0	0	350	0	0	0	0	0	0	~~135~~	155	0
3	0	0	0	0	0	0	0	140	135	0	0	0
4	0	0	0	0	155	0	0	0	0	0	0	0
5	0	92	0	0	0	0	0	210	490	180	0	0
6	0	0	0	125	0	0	140	250	0	0	0	0
7	0	0	0	0	0	0	0	0	0	0	0	150
8	0	0	0	0	0	600	0	0	0	0	185	0
9	0	0	175	200	0	0	0	0	490	0	0	0
10	0	0	0	0	0	0	0	150	0	0	190	0
11	0	0	0	0	0	0	0	0	0	0	0	0
12	135	0	0	0	0	570	0	0	400	160	0	0
13	0	0	0	0	0	0	200	0	0	0	0	0
14	0	165	0	0	800	0	0	0	0	0	0	150
15	0	0	0	0	0	400	0	0	0	0	0	0
16	0	0	150	0	0	0	0	0	0	0	149	0
17	0	0	0	0	0	0	0	190	0	200	0	0
18	0	0	0	145	0	0	0	0	0	0	0	0
19	135	0	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	0	140	0	0	0	0	0
21	0	0	0	0	290	0	0	0	175	0	0	0
22	0	0	0	0	0	0	0	0	0	155	0	0
23	0	0	150	0	0	0	0	0	0	0	140	145
24	0	0	0	0	0	0	0	0	0	0	0	0
25	0	0	0	490	0	0	0	0	0	0	0	0
26	135	0	0	0	0	0	0	0	0	350	0	0
27	0	0	0	0	500	0	120	190	0	0	0	0
28	0	0	0	0	0	0	0	0	170	0	180	0
29	0	0	0	0	0	380	0	0	0	0	0	0
30	0	0	0	0	490	0	0	0	0	0	0	0
31	0	0	150	0	0	0	0	0	0	0	0	145
Mean Sec. Ft.	132.5	128.5	195	240	447	487	150	188	310	203	166	147
Total Ac. Ft.												

TOTAL FOR _____ ACRE FEET

FORM NO. 201 5 M

STATE OF UTAH
OFFICE OF STATE ENGINEER

Daily Discharge in Second Feet of Surplus Canal

at 21st South Dam for Lower Jordan 1991

Day	Jan	Feb.	Mar.	April	May	June	July	Aug.	Sept.	Oct.	Nov	Dec
1	156	0	0	0	0	0	0	0	0	0	0	0
2	0	0	267	0	0	1360	0	0	0	0	156	0
3	0	0	0	0	0	0	0	141	227	0	0	0
4	0	0	0	0	310	700	0	0	0	0	0	0
5	0	190	0	0	0	0	0	601	601	265	0	0
6	0	0	0	125	0	0	208	0	0	0	0	0
7	0	0	0	0	0	0	0	0	0	0	0	175
8	0	0	0	0	0	950	0	0	0	0	190	0
9	0	0	126	190	0	0	0	0	601	0	0	0
10	0	0	0	0	0	0	0	126	0	0	227	0
11	0	0	0	0	0	0	0	0	0	0	0	0
12	150	0	0	0	0	1050	190	0	503	227	0	0
13	0	0	0	0	1050	0	0	0	0	0	0	0
14	0	0	0	0	0	0	0	0	0	0	0	175
15	0	190	0	0	0	775	0	0	0	0	0	0
16	0	0	126	0	0	0	0	0	0	126	190	0
17	0	0	0	0	0	0	0	141	0	0	0	0
18	0	0	0	156	0	0	0	0	0	0	0	0
19	150	0	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	454	208	0	0	0	0	0
21	0	0	0	0	405	0	0	0	173	0	0	0
22	0	0	0	0	0	0	0	0	0	193	0	0
23	0	126	126	0	0	0	0	0	0	0	156	156
24	0	0	0	0	0	0	0	0	0	0	0	0
25	0	0	0	900	0	0	0	0	0	0	0	0
26	89	0	0	0	0	0	0	0	0	0	0	0
27	0	0	0	0	750	0	126	135	0	0	0	0
28	0	0	0	0	0	227	0	0	204	400	227	0
29	0	0	0	0	0	0	0	0	0	0	0	0
30	0	0	0	0	552	0	0	0	0	0	0	0
31	0	0	135	0	0	0	0	0	0	0	0	150
Mean Sec. Ft.	136	168	156	342	613	788	183	228	384	226	191	164
Total Ac. Ft.												

TOTAL FOR _____ ACRE FEET

FORM NO. 201 5 M

STATE OF UTAH
OFFICE OF STATE ENGINEER

Daily Discharge in Second Feet of Jordan River

at 21st South Dam + 17th so. for Lower Jordan 19 ____

Day	Jan.	Feb.	Mar.	April	May	June	July	Aug.	Sept.	Oct.	Nov.	Dec.
1	100	0	0	0	0	0	0	0	0	0	0	0
2	0	0	141	0	0	295	0	0	0	0	123	0
3	0	0	0	0	0	0	0	132	114	0	0	0
4	0	0	0	0	105	0	0	0	0	0	0	0
5	0	150	0	0	0	0	0	190	186	140	0	0
6	0	71	0	90	0	0	132	0	0	0	0	0
7	0	0	0	0	0	0	0	0	0	0	0	135
8	0	0	0	0	0	255	0	0	0	0	0	0
9	0	0	105	96	0	0	0	0	170	0	165	0
10	0	0	0	0	0	0	0	168	0	0	150	0
11	0	0	0	0	0	0	0	0	0	0	0	0
12	110	0	0	0	0	265	0	0	155	141	0	0
13	0	0	0	0	0		159	0	0	0	0	0
14	0	0	0	0	177	0	0	0	0	0	0	140
15	0	0	0	0	0	255	0	0	0	0	0	0
16	0	114	114	0	0	0	0	0	0	0	132	0
17	0	0	0	0	0	0	0	177	0	155	0	140
18	0	0	0	96	0	0	0	0	0	0	0	0
19	110	0	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	205	132	0	0	0	0	0
21	0	0	0	0	132	0	0	0	132	0	0	0
22	0	0	0	0	0	0	0	0	0	150	0	0
23	0	114	105	0	0	0	0	0	0	0	132	123
24	0	0	0	0	0	0	0	0	0	0	0	0
25	0	0	0	123	0	0	0	0	0	0	0	0
26	114	0	0	0	0	0	0	0	0	0	0	0
27	0	0	0	0	220	0	132	159	0	168	0	0
28	0	0	0	0	0	0	0	0	140	0	140	0
29	0	0	0	0	0	168	0	0	0	0	0	0
30	0	0	0	0	219	0	0	0	0	0	0	0
31	0	0	110	0	0	0	0	0	0	0	0	114
Mean Sec. Ft.	108.5	98	115	99	170	240	139	165	143	150	140	132
Total Ac. Ft.												

TOTAL FOR _____ ACRE FEET

FORM NO. 201 5 M

STATE OF UTAH
OFFICE OF STATE ENGINEER

Daily Discharge in Second Feet of Surplus Canal

at Husted Dam for Jordan 1991

Day	JAN.	FEB.	mar.	april	may	June	July	aug.	Sept.	Oct.	nov	Dec
1	125	0	0	0	0	0	0	0	0	0	0	0
2	0	0	226	0	0	0	0	0	0	0	125	0
3	0	0	0	0	0	0	0	27	110	0	0	0
4	0	0	0	0	290	0	0	0	0	0	0	0
5	0	140	0	0	0	0	0	500	500	110	0	0
6	0	0	0	125	0	0	106	0	0	0	0	0
7	0	0	0	0	0	0	0	0	0	0	0	120
8	0	0	0	0	0	900	0	0	0	0	0	0
9	0	0	125	195	0	0	0	0	500	0	145	0
10	0	0	0	0	0	0	0	50	0	0	175	0
11	0	0	0	0	0	0	0	0	0	0	0	0
12	100	0	0	0	0	0	0	0	350	135	0	0
13	0	0	0	0	0	1000	89	0	0	0	0	0
14	0	155	0	0	900	0	0	0	0	0	0	120
15	0	0	0	0	0	700	0	0	0	0	0	0
16	0	0	130	0	0	0	0	0	0	0	125	0
17	0	0	0	0	0	0	0	68	0	30	0	0
18	0	0	0	140	0	0	0	0	0	0	0	0
19	135	0	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	0	115	0	0	0	0	0
21	0	0	0	0	356	0	0	100	100	0	0	0
22	0	0	0	0	0	0	0	0	0	100	0	0
23	0	0	120	0	0	0	0	0	0	0	125	100
24	0	0	0	0	0	0	0	0	0	0	0	0
25	0	0	0	850	0	0	0	0	0	0	0	0
26	110	0	0	0	0	0	0	0	0	395	0	0
27	0	0	0	0	610	0	0	0	0	0	0	0
28	0	0	0	0	0	0	47	52	65	0	155	0
29	0	0	0	0	0	0	0	0	0	0	0	0
30	0	0	0	0	510	150	0	0	0	0	0	0
31	0	0	140	0	0	0	0	0	0	0	0	100
Mean Sec. Ft.	117	147	157	327	533	587	89.5	125	271	154	141.6	110
Total Ac. Ft.												

TOTAL FOR _____ ACRE FEET

January 15, 1992

The 1991 commissioner report for the Lower Jordan Water system.

The water year for 1991 was a little better than the past 3 years, The precipitation was up to near normal, but do the preveious drought years the water didn't go as far as normal.

Nearly all the Duck Clubs completed there dyke repair, except Jordan Fur + Reclamation + Farmington Bay.

Good rain's in September made it so every one was able to fill there pond's by ~~September~~ Oct. 5th.

January 26th was the low stream flow in the system taken at 21st south + the river. 203 C.F.S.

June 2nd was the high strem flow. taken a 21st 1655 C.F.S.

The average flow for the year at the recorded gaging station were.

Jordan river at 17th South	141 C.F.S.	(264 C.F.S. Total Dec. 31, 1991)
Cudahay lane + Jordan river	224 C.F.S.	
Surplus canal at 21st south	298 C.F.S.	
Husted dam + Surplus canal	229 C.F.S	

Ambassador cut. + Gilmore and State canal stations were cheked several times but not recorded.

On October 12th the stream flow in the surplus canal was cut down so the Kern river pipe line could be installed across the canal. It was down for 4 days.

We still have a few problem's in the system the ambassador cut stream bed is is still pluged up. the lower Jordan + the State canal need to be cleaned out. they are full of sand.

Fred Lewis from the North Point Duck Club is very unpappy. with the Rudy duck Club. the way they hold and discharge there water.

I think this problem should be discussed in this meeting.

Sorver Jordan Water commissioner
John E Moesser