June 23, 1970

Capital Reef Lodge - Capital Reef Monument.

Claire Bird
McKeel
Wallace

HCL summed up.
water rights as developed and maintained.
distribution change may be required
new look
Board of Health

1. Can we operate as was
2. More desirable to operate in New manner

Bird
I Beaver & muscrat - won't let Bird trap. (1963 till now)
II Plant Growth along ditch - park Ser. won't let Bird cut growth.
III Lodge built in 1946
IV Won't let Bird clean ditch with tractor as before.
V blocked ditch and filled up ditch in May.
VI ~~Give~~ Bird wants 2" connection and do away with ditch.

McKeel - Wallace.
I Park Service maintained with shovels against policy.
II Bird maintained in winter time. for culinary use & fire protection.

III 1970 Park Service decided not to use ditch & informed Bird. Bird wanted to use tractor & herbicides Park service couldn't permit.

IV ditch ½ mile long.

IV alternatives to ~~maintain~~ give Bird water.

1. Shorter pipeline across a shorter distance. [¼ mile long + pump perhaps]
   a. Special use permit
   b. Bird's expense.
      1. Bird will not expend any money (~~1000~~ if park service install pump. 2½ inch pipeline)

Park service can't put money in but will grant access for maintainance.