Strawberry River Commissioner Leo L. Brady 1961

Name of Canal or Ditch	Company or Individuals.	Description of Diversion Dam.	Description of Headgate	Description of Measuring Device.	Condition of Canal or Ditch	Recomendations & Remarks
Currant Creek Feeder	Strawberry Water User's Association	Pickup Canal which intercepts Currant Creek.	Conc. or Rubble Masonary Spillway Structure from Canal to Creek.	U.S.G.S. gaging Station.	Good.	Inaccessable Approx. 20 miles up Currant Creek from Currant Creek lodge on Highway 40
Lindsay	Elmer R. Moon	Rock & Brush	Wood Box w/Wood gates. good Condition	None	Good.	12" Parshall Flume. Source Currant Creek
Smith	Emory Smith	None	Wood Box good Condition.	None	Good	12" Parshall Flume. Source Currant Creek
Lodge	Walter E. Weist.	Loose Rock & Earth.	Culvert no Intake gate.	None.	Good	9" Parshall Flume. Source Currant Creek. 15" C.M. Pipe w/101 gate & Conc. Headwall.
Murdock-Forrer	Alva P. Murdock. Tri-State Land and Cattle Co.	Rock and Brush.	21" C.M. Pipe w/101 Headgate.	None	Beaver Trouble lots of Willows.	Diversion Headgate equipped with Calco Meter gate. But Sufficient head isn't available to make operate. 24" Parshall Flume. Source Currant Creek
Muir	Alden Muir Tri-State Land and Cattle Co.	Large Rock	Wood Box good Condition	18" Parshall Flume (Metal)	Good.	Present Facilities OK Source Currant Creek.
Geo. Muir	Tim C Butters	None	C.M. Pipe. w/Pull Type Slide gate	None	Good.	9" Parshall Flume has been purchased and will be installed. Source Red Creek.
Red Creek Canal.	Red Creek Irrg. Co.	Large Rock	C.M. Pipe w/101 Headgate.	4 ft. Metal Parshall Flume.	Good.	Present facilities OK Source Red Creek
Red Creek Reservoir	Red Creek Irrg. Co.	Earth Structure	Metal Side Gate	3' Parshall Flumes	—	A three foot Parshall Flume (Metal) has been installed at both Inlet and outlet to the Reservoir.
Diamond S Ranch Upper	Smith & Kelly Feed Co. Address Unknown	Loose Rock	C.M. Pipe w/101 gate Screw lift	None	Good	12" Parshall Flume recommended Source Red Creek
Diamond S. Ranch Lower.	"	Loose Rock.	"	None	Good	" " " " " " "

Strawberry River. Commissioner Leo L. Brady 1961

Name of Canal or Ditch	Company or Individuals	Description of Diversion Dam	Description of Headgate	Description of Measuring Device	Condition of Canal or Ditch	Recommendations & Remarks
Poulsen	Mont Poulsen Milton " Ken Ivie	Sheet Steel Piling w/ Rock Backfill	Cone Structure w/ Slide screw type Headgate.	None	Diversion Dam needs Maintenance work done.	12" Parshall Flume
Rasmussen	Gene Rasmussen	Pump	—	None.		Hasn't been used since 1959
Peatross	Wm Peatross O.C. Mickelson Thomas Appa Arnold Robbins	Pump	—	None	Good	12" Parshall Flume.
Winslow	Thomas Appa	Wood Diversion Dam	Wood gate in side of Diversion Dam	None.	Beaver Problems.	Provide adequate control of Headgate. 12" Parshall Flume.
Mitchell	Loren Mitchell	Pump	—	None	Good	12" Parshall Flume.
Merrill	Porter L. Merrill	Pump	—	None	Good Except Flat Grade	12" Parshall if grade will allow installation.
Collett	Byron Collett.	Pump	—	None	Flat Grade.	Only serves Approx 3 acres 9" Parshall if possible.

Straw berry River — Commissioner Leo L. Brady — 1961

Name of Canal or Ditch	Company or Individuals	Description of Diversion Dam	Description of Headgate	Description of Measuring Device	Condition of Canal or Ditch	Recommendations & Remarks.
Wm Hayes	Wm Hayes	Rock & Brush	Wood Box	None	Fair	18" C.M. Pipe w/101 Headgate and 12" Parshall Flume. w/Conc Headwall
Olsen #1	Thomas & Ralph Olsen	Brush.	Screw type Headgate good Conc. Structure Abandoned Divert below Structure without any Headgate.	None	Fair.	18" C.M. Pipe. w/101 Headgate and 12" Parshall Flume
Olsen #2	"	Logs on Cable.	None	None	Good	Same as #1
Ivie – Peterson	Raleigh Ivie Delmar " Ina M. Peterson	Sheet Steel Piling w/large Rock Backfill	C.M. Pipe w/Slide Screw Type Headgate	None	Very Flat Grade.	12" Parshall Flume if location for installation can be found.
Baum – Mezenen	Clarence Baum Albert Mezenen	Sheet Steel Piling.	C.M. Pipe w/Slide Screw gate. Good Structure	None	Good.	12" Parshall flume.
Lott-Bates	Charles L. Lott Wilbur Bates	Tree & Brush	Conc. Box w/Wood gate.	None	Beaver Problems at Heading.	Need Headgate with positive control attached to conc. Box. & 12" Parshall Flume
Rowley	Bert Rowley Est.	Tree & Brush & Straw.	None	None	Ditch needs Maintenance to control Flooding in Brush area along River	18" C.M. Pipe w/101 Headgate w/Conc Headwall 12" Parshall Flume.
PW & Peter Rasmussen	Ralph Ivie Glen Ivie.	Sheet Steel piling.	None	None	River has washed around left Bank of Steel piling at Diversion Dam.	18" C.M. Pipe w/101 Headgate w/Conc Headwall 12" Parshall Flume.
Williams	W. Ed Williams	Log & Brush	None	None	Good.	18" C.M. Pipe w/101 Headgate and Conc. Headwall 12" Parshall Flume.
Wheeler	Verl Ivie.	Sheet Steel Piling.	Slide gate Screw Type.	None	Very Flat Grade	12" Parshall if location for setting can be found. otherwise a rating Flume may have to be used.

Strawberry River — Commissioner Leo L. Brady — 1961

Name of Canal or Ditch	Company or Individuals	Description of Diversion Dam.	Description of Headgate	Description of Measuring Device.	Condition of Canal ditch.	Recommendations & Remarks.
Ferron #1	Fred A. Ferron.	None	24" C.M. Pipe w/101 gate Screw lift.	None	Good	12" Parshall Flume. Source Red Creek.
Snyder	Alfred Giles	None	None	None	Good.	Inacessable except by truck or Jeep During low periods of Flow. You have to cross the stream about 4 times no bridges. 12" Parshall Flume Source Strawberry River
Remund #1	Glen Remund	Rock & Brush	24" C.M. Pipe w/Pull Type Slide gate.	None	Good	12" Parshall Flume.
Remund #2	Lloyd Remund	Placed Rock (Large) Excellent Structure.	24" C.M. Pipe w/101 Headgate Screw lift.	None	Good	Flat ditch grade & Not much bank on ditch. Irrg. if Field starts immediately at Diversion Point. 18" Parshall Flume may work on Head ditch approx. 300 ft from heading.
Fred Hayes	Fred Hayes	Log crib & Rock.	Wood Flashboards	None	Good	12" Parshall Flume Water is also being diverted from Strawberry River to serve lands irrigated on North side of River. Filing has a point of Diversion for all water to be from Huintaquin Creek. (15" C.M. Pipe w/101 Headgate needed)
Peatross	Wm Peatross	None	Conc. Structure w/101 Headgate Screw Type.	None	Good	12" Parshall Flume Source Huintaquin Creek
Ferron	Fred A. Ferron	Log and Rock	24" C.M. Pipe w/101 Headgate. Screw lift! Rubble Masonary Headwall	None	Beaver Trouble.	12" Parshall Flume. Inacessable you have to wade the river to get to it. — not possible during high Flows.
Koyen #1 Upper.	Wesley Koyen	Rock & Brush	18" C.M. Pipe w/ Rubble Masonary Headwall	None	Beaver Trouble.	12" Parshall Flume.
Mott.	Unknown	Rock & Brush	None	None	Fair.	This farm is diverting water at two Div. points one on south side and one on North side of River. These div. points were just reactivated during 1961 Irrg. Season. I only know of one filing for this farm. 12" Parshall Flume & C.M. Pipe w/Headgate
Koyen #2	Wesley Koyen	Rock & Brush	None	Conc.	Good	12" Parshall Flume & 18" C.M. Pipe w/ Screw type Headgate w/ Concrete Headwall