Boulder (Deer Creek)

Tuesday - Aug 22, 1972

Petition
Scott
McDonald
Co.

1. Ditch (conditional)
2. Garkane power (fluctuation) 10/30 release
3. Measureing devices
   a. improper installation
   b. leaking
   c. no headgates.

investigation on June 11, 1972 Pond dry - what could Co. do (6-18-72 P dry)

Define Problem
What we can do
set time schedule

McDonald

1. Problems in system
   a. inequities in distribution
   b. articles of incorp. basis for water division.
2. Violation
   a. failure of Co. to maintain ditches. (Redwing Ranch 5-24-72) damage (leak).

(wake leak already there)

3. Headgates & Measureing devices.
   a. not proper between upper & lower Boulder.

division

Jackson.
Most people on board.

No system can operate without
headgates
Measuring devices
delivery schedule
Commissioner
assessment.
channel loss

water right picture

of schedule of rights

Norm Jackson

1. determine apportionment
2. inflow outflow from Garbana ?
facilities.
3. water measuring devices
& headgates.
4. handling storage right
(spectacle)
5. transmission channel loss

Private & Co.

Weirs

Spectacle, above West Fork Pond Boulder,

East Fork Boulder & Bear Creek,