Pg 67 Hiring 1918 water up to 1¼" Top 1st flash

Pg 68 " 1915 leakage Drawn to 20 S.F.

Pg 69 not below 20 S.F.

Pg 78 just busy

Pg 81 more comprehensive work

Pg 82 Drawn down T battery of 1st flash

Pg 111 Hunterdon 16 S.F. Jan River

P 113 Pump July & Aug 10 & 11

Pg 116 above 2 crack

Pg 138 Thompson not enough

Pg 140 " leakage Trap Dam

" 130 " more leakage generally than last yr

Pg 68 Drawn T. 20 S.F.

Pg 82 Drawn to battery 1st Flash

28-29-30

31-32-33 & 41

40