Burnt Fork - Beaver Creek

STREAM DIVERSION REPORT

STREAM _____ FROM May 1984 TO oct 1984

TITLE _____ DIVISION _____ DISTRICT _____

SHEET 1 of 1 SHEETS

PRIORITY REGULATED TO: May 25 June 15 July 20

DITCH	DEVICE	SIZE	DATE - GAGE	DATE - CFS	DATE - GAGE	DATE - CFS	DATE - GAGE	DATE - CFS	DATE - GAGE	DATE - CFS	DATE - GAGE	DATE - CFS	DATE - GAGE	DATE - CFS	DATE - GAGE	DATE - CFS	REMARKS
Stoll #1				.57		.57		.57									
Leavitt			There is a question as to whether this ditch actual exists research needs to be done														
Stoll #2				1.43		1.43		1.43									
Home	This ditch is Questionable as to where it is and who uses it																
Preemption				1.14		1.14		1.14									
Gamble				10.52		18.00		10.52									
Widdop				2.57		5.00		2.57	water being used Before Measuring device due to Make shift gathering Basin.								
Anson-Driskell				3.63		3.63		3.63									
Anson																	
Baldy Spring				3.00		3.00		3.00									
High line				3.85		3.85		3.85									
Wyman				4.80		8.00		4.80	This has an old wood Headgate. It should be replaced or repaired								
Kirkendall				4.13		4.13		4.13									
Musk rat	Headgate washed out during 1983. No use Since																
Ike Canal				12.00		20.00		12.00									
W. Stoll Ditch				1.64		1.64		1.64									
Welch				2.31		2.31		2.31									
Perkins				6.74		5.50		6.74									
Midway	~~Headgate washed out No use during 1984~~			~~6.48~~		~~6.48~~		6.48									
Hallet				1.41		1.41		1.41									
Gillis	Headgate washed out No use during 1984																
Interstate				30.00		30.00		30.00	This was Burnt Fork water. In Addition 20CFS from Beaver Meadows until Reservoir was drained due to Dam construction Approx July 25, 1984								
Baldy Spring St.				11.00		11.00		11.00									