Div. assembly is not stable

Dirt sluffs into inlet

Inlet Lower Than Canal

← poor ditch Banks From Div. to Weir

Bad Seal around Weir

Leakag From Div going over Weir

Res. Near Div Site is Full

Div. Stem

Poor bank repair
Choose Sand &





Weir

out Let Pipe

out Let Chanel

Gate

Wilmar Parish 4-r diversion after renovation Work 1987, Deep Creek 43 Area.

16