

DIVISION OF WATER RIGHTS

In the matter of: **Gay Ditch Co.**

**Blue Water Marine
PO Box 390
Helper, UT 84526**

**Joy Gipson
PO BOX 168
Helper, UT 84526**

**Lowdermilk Rock Products of Utah, Inc.
PO BOX 509
Helper, UT 84526**

**John C. Marchello
1776 Castle Ave
Price, UT 84501-2026**

**Robert Radakovich
2564 S. Corral Dr.
Grand Junction, CO 81505**

**Sacco Brothers Land & Livestock
1655 W 2100 N
Helper, UT 84526**

RESPONDENTS

**NOTICE OF PARTIAL
COMPLIANCE**

SEAA No. 1325

DISTRIBUTION ACCOUNTS: 101684;
101686; 101683; 101687; 101682; 101680;
101685; 101681; 101688; 101689

WATER RIGHTS: 91-1754; 91-1755; 91-
1756; 91-1757; 91-1775; 91-1776; 91-1777;
91-1778; 91-1779; 91-1780; 91-1781; 91-
1782; 91-1783; 91-1784; 91-1785; 91-1786;
91-1787; 91-1788; 91-1789; 91-1790; 91-
1791; 91-1792; 91-1795; 91-1796; 91-1797;
91-1798; 91-1799; 91-1800 – 1808; 91-719-
724; 91-726-728; 91-730-732

Gay Ditch Water Users:

The above-listed Respondents pay the annual distribution assessments for water distributed to the Gay Ditch. The Division understands the Respondents to be the current users of the water and as such, each received a Measurement Device Notice last August and is now receiving this Notice of Partial Compliance.

Water from the Price River is distributed to the respondents via the Gay Ditch under the above-listed water rights. The commissioner measures the water distributed to the Gay Ditch at the Parshall flume located next to Bill Branson's house just off the Helper Highway. The Division

SCANNED

re-inspected the measurement device on the Gay Ditch and determined that while the return gate located immediately above the flume remains completely closed, the existing Parshall flume is a sufficiently accurate measuring device.

The Respondents are hereby notified that as long as the Gay Ditch diversion is operated with the waste gate completely closed, **and a stilling well is installed adjacent to the existing flume** no later than April 1, 2010, the existing Parshall flume is a sufficiently accurate measuring device and will not need to be replaced.

The equitable distribution of water from the Price River in accordance with existing water rights is a concern to Division as well as to the Respondents. To that end we appreciate your diligent attention to this matter and thank you for your cooperation. If you have any questions concerning this letter please contact Sue Odekirk, Distribution Engineer at (801) 538-7431 or Marc Stilson, Southeast Regional Engineer at (435) 613-3750.



Sue Odekirk, P.E.
Distribution Engineer

cc: Marc Stilson, Tom Bruno, Robert Davis

SCANNED

9/30/2009

GAY DITCH FLUME


FLUME - 2.8 cfs.

8%

A - 0.34'
H_A - 0.82
V_A - 1.18 ft/s.
Q_A - 0.653

1.6 cfs.
- 0.62
- 0.73
- 0.306
3.4%

B - 1.01'
H_B - 0.82
V_B - 1.56
Q_B - 0.863



C - 1.69'
H_C - 0.8
V_C - 1.24
Q_C - 0.670

0.59
1.13
Q - 0.45

D - 2.36'
H_D - 0.78
V_D - 0.99
Q_D - 0.521

0.55
0.71
Q - 0.264

Q_T = 2.71

Q_{TOT} = 1.4

Jesse -
Will you please
scan these
notes into
SEAA 1325 too?
THX Sui ☺

Flame - 1.6 cfr.

A

SCANNED