



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF WATER RIGHTS

Michael O. Leavitt
Governor

Robert L. Morgan
Executive Director

Jerry D. Olds
State Engineer

Southeastern Area
453 South Carbon Avenue
PO Box 718
Price, Utah 84501-0718
(435) 637-1303 telephone
(435) 637-7937 fax
www.nr.utah.gov

May 5, 2003

RECEIVED
MAY - 7 2003
WATER RIGHTS
SALT LAKE

Bryner-Ploutz Ditch
c/o Steve Giacoletto
101 West 200 North
Helper, Utah 84526

Dear Steve:

Re: Parshall Flume

Bob Davis has had some concern about the accuracy of the Parshall Flume on the Bryner-Ploutz Ditch. As a result, we made several measurements earlier today. According to the measurements, the flume is reading approximately 40% high, meaning you are being charged for water you are not receiving. At the last reading today, the flume read 1.64 cfs, and the actual flow was 0.97 cfs.

Therefore, I am writing this letter to request that you replace the flume at your earliest convenience with a 12-inch flume, if one can be found, and move the location to the south end of the field. I would suggest you meet with Bob Davis and choose an appropriate location. I would also suggest you contact Frank Saccomano and see if they have a flume they would be willing to give you to be placed in the ditch.

If you have any questions, please feel free to contact me at your convenience.

Sincerely,

Mark P. Page
Regional Engineer

pc: Bob Davis
Lee Sim

MPP/mjk