

COMMISSIONER'S MONTHLY REPORT

Commissioner \_\_\_\_\_

2:00 PM

Date July 31 1967  
 Report for Month of July 1967

10:30 AM

Source and Point of Measurement	Day of the Month														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
I. Boardman Springs															
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)					3.3										3.95
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)					—										—
#3. Church ditch near to heading					1.295										0.49
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)					1.535										1.79
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake					2.77										5.73
II. Thomas Spring															
#5. Above the Olsen house below the tracks					1.41										1.53
III. Drain															
#6. Drain Channel near Railroad Shop and Burningham properties					1.0										0.5
IV. #8. Levie Ditch - Water to Church Farm, etc.					5.66										0.0
V. #9. Pump Water at Church Welfare Farm					0.0										0.0

For key to location numbers see drawing P-5107

Submitted by

E. Lewis Allen  
 E. Lewis Allen

ARM