



1636 West North Temple • Salt Lake City, UT 84116 • 801-533-6071

\* M E M O R A N D U M \*

TO: File  
FROM: Richard B. Hall, P. E., Directing Engineer  
SUBJECT: Field Review of the Lower San Pitch River Distribution System  
DATE: SEPTEMBER 24, 1984

A field review of the subject system was undertaken on September 18, 1984 with the following in attendance:

Donny Christensen  
M. Stanley Adams

Kirk Forbush  
Jerry L. Bronicel

Richard B. Hall

The following items were noted and/or discussed:

- 1) Palisades Reservoir Diversion - The Parshall Flume approach channel needs cleaning. Feeds Highland Canal.
- 2) Gunnison Reservoir - Gaging station below the dam. Feeds Highland Canal.
- 3) Ninemile Reservoir - Feeds Highland Canal.
- 4) City Ditch - Adequate Parshall Flume.
- 5) Old Field Ditch - Adequate Parshall Flume.
- 6) New Field Ditch (from Twelvemile) - Adequate Parshall Flume.
- 7) Highland Canal out of Twelvemile - Adequate Parshall Flume.
- 8) Mayfield North Ditch - Parshall Flume needs to be raised.
- 9) The Mayfield Irrigation Company has numerous diversions, which will be abandoned when the dam, which failed in the spring of 1984, is reconstructed to feed their pressure system.

cc: Jerry L. Bronicel