

Price Utah
Aug. 10 1960

Mr. Donald C. Norseth,
Distribution Engineer
State of Utah
Salt Lake City, Utah


Dear Mr Norseth:

Re: Boyd Marsing vs Country Club.

Mr. Marsing and I went over the area in question and I feel there is a decided interference in the spring flow for two reasons; 1st. the increase of size and depth of their sump. 2nd. their landscaping has made a bog and swamp just below their sump.

As to their method of diverting and date of change I can say this; it was after the flood in 1952 they put in their large pump.

Very truly yours,


Harvey Thomas,
Commissioner, Price River

