



STATE OF UTAH  
NATURAL RESOURCES  
Water Rights

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Robert L. Morgan, State Engineer

Southeastern Area • 453 S. Carbon Avenue • P.O. Box 718 • Price, UT 84501-0718 • 801-637-1303

April 13, 1989

RECEIVED

APR 17 1989

Doug Farnsworth  
2130 South Shumway Lane  
Moab, Utah 84532

WATER RIGHTS  
SALT LAKE

Re: Head Gate - Mill Creek Diversion - South Mesa

Dear Doug:

At the annual meeting of the Mill Creek Distribution System held April 5, 1989, there was some discussion about the diversion structures that needed to be repaired on the system. Your control structure on Mill Creek, at the South Mesa Diversion, was mentioned. The control gate has not been operational for some time. A letter was written last year (to FHA) requesting that the necessary repairs be made. For whatever reason, it has yet to be accomplished. Because of the eminent dry water year ahead, all of the diversion control structures on the system must be operational along with an accurate measuring device. Your flume is probably operating satisfactorily.

Therefore, before any water will be delivered through the South Mesa Ditch this spring, this work must be accomplished. Robert Byrnes has been so instructed concerning this matter.

If you have any questions, please feel free to contact me.

Respectfully,

Mark P. Page  
Area Engineer

cc: Mill Creek Distribution System  
Attn: Robert Byrnes, Commissioner  
P.O. Box 248  
Moab, Utah 84532

Division of Water Rights  
Attn: Lee Sim, Director of Distribution  
1636 West North Temple  
Salt Lake City, Utah 84116

Certified Mail