



STATE OF UTAH
NATURAL RESOURCES
Water Rights

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Robert L. Morgan, State Engineer

Southeastern Area • 453 S. Carbon Avenue • P.O. Box 718 • Price, UT 84501-0718 • 801-637-1303

April 13, 1988

Farmer's Home Administration
Attn: Jean Robinson
P.O. Box 10
Monticello, Utah 84535

Re: Kay Young Property - Mill Creek
Diversion Ditch Measuring Device

Dear Ms. Robinson:

At the annual Mill Creek Distribution System water users meeting held April 6, 1988, Commissioner Bob Byrnes indicated that the headgate and parshall flume used for the Young Property is in need of repair prior to water being diverted during this coming irrigation season. Therefore, I am requesting that some attention be given to this matter and the needed repairs made as soon as possible.

I would appreciate being advised when this work is completed. If you have any questions concerning this matter, please contact me.

Sincerely,

Mark P. Page
Area Engineer

cc: Division of Water Rights
Attn: Lee Sim, Director of Distribution
1636 West North Temple
Salt Lake City, Utah 84116

Mill Creek Distribution System
Attn: Bob Byrnes, Commissioner
P.O. Box 248
Moab, Utah 84532