

COMMISSIONER'S MONTHLY REPORT

Commissioner \_\_\_\_\_

Date Sept 15 1966  
 Report for Month of Aug 1966

| Source and Point of Measurement   | Day of the Month |   |   |       |   |   |   |   |   |    |    |    |    |    |    |    |
|---|------------------|---|---|-------|---|---|---|---|---|----|----|----|----|----|----|----|
|   | 1                | 2 | 3 | 4     | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 31 |
| I. Boardman Springs   |                  |   |   |       |   |   |   |   |   |    |    |    |    |    |    |    |
| #1. Pacific States Cast Iron Pipe Co.<br>(down stream from Pipe Line)   |                  |   |   | 2.37  |   |   |   |   |   |    |    |    |    |    |    |    |
| #2. Boardman Springs Channel by U. S. Highway #91<br>(This reading does not include #1 or Pacific<br>States Cast Iron Pipe Co. Water)       |                  |   |   | 0.775 |   |   |   |   |   |    |    |    |    |    |    |    |
| #3. Church ditch near to heading  |                  |   |   | 0.10  |   |   |   |   |   |    |    |    |    |    |    |    |
| #4. Boardman Spring water before it joins Thomas<br>Spring (This has a pick up of miscellaneous<br>small springs along the RR right-of-way) |                  |   |   | 0.298 |   |   |   |   |   |    |    |    |    |    |    |    |
| #7. Boardman Spring Waste Channel to #9 (pump)<br>and to Utah Lake  |                  |   |   | 0.675 |   |   |   |   |   |    |    |    |    |    |    |    |
| II. Thomas Spring   |                  |   |   |       |   |   |   |   |   |    |    |    |    |    |    |    |
| #5. Above the Olsen house below the tracks  |                  |   |   | 2.66  |   |   |   |   |   |    |    |    |    |    |    |    |
| III. Drain  |                  |   |   |       |   |   |   |   |   |    |    |    |    |    |    |    |
| #6. Drain Channel near Railroad Shop and<br>Birmingham properties   |                  |   |   | 1.5   |   |   |   |   |   |    |    |    |    |    |    |    |
| IV. #8. Levie Ditch - Water to Church Farm, etc.  |                  |   |   | 2.96  |   |   |   |   |   |    |    |    |    |    |    |    |
| V. #9. Pump Water at Church Welfare Farm  |                  |   |   | 0.0   |   |   |   |   |   |    |    |    |    |    |    |    |

For key to location numbers see drawing P-5107

Submitted by

*[Signature]*  
 E. Lewis Allen

*Note how levee ditch users have a Fall stream without any water from Boardman Springs. Pa State uses Nat. Boardman. This is historic. Note these two waters have always divided.*