



Lyle Ford, Inc.

Consulting Services

3544 East Oaks Drive
Salt Lake City, Utah 84124

Office Phone: 801-278-3505
Res. Phone: 801-277-4423

LYLE S. FORD
President

SEP 27 1993

WATER RIGHTS
SALT LAKE

September 15, 1993

State of Utah
Dept. of Natural Resources
Division of Water Rights
1636 West North Temple, Suite 220
Salt Lake City, Utah 84116-3156

RE: City of South
Salt Lake Wells
System 18032

Attention: Robert L. Morgan, P.E.

Dear Mr. Morgan:

The attached well water analysis reports are on water samples collected from the City of South Salt Lake wells on August 23, 1993.

1. Well Information:

- . Bolinder Well Source 02
- . Davis Well Source 03
- . 3rd East Well Source 06
- . 4th East Well Source 05
- . 7th East Well Source 07

2. The samples were collected by Marvin Taylor from the City of South Salt Lake who is trained and qualified to collect water samples.

3. The analyses were performed by ChemTech Labs (see attached certificate).

4. Field Measurements:

	<u>pH</u>	<u>Cond.</u>	<u>Temp. F</u>
Bolinder	6.90	700	63
Davis	6.80	540	63
3rd East	6.90	930	68
4th East	7.10	770	64
7th East	6.70	950	64

5. Inorganic Analysis:

see attached Lab reports.

State of Utah
September 15, 1993
page two

6. Volume from each Source:

see attached report.

Sincerely,


Lyle Ford, Inc.

LSF:jcf

encls.